Total Home Inspection Services Property Inspection Report



810 E. Rte 66 Space 132, Phoenix AZ, 91351 Inspection prepared for: John Smith Agent: Christine Johnson - Century 21

Inspection Date: 10/25/2006

Inspector: Jack Jackson 1234 Inspection Rd. Phoenix AZ, 94111 Phone: 555-555-1212 http://www.TotalHomeInspectionServices.biz

Report Summary

Interior				
Page 2 Item: 7	Doors	did not latch, sticks at the jamb FR		
Page 3 Item: 18	Window Condition	frame separating from the glass south LR		
Bedroom				
Page 4 Item: 7	Doors	did not latch#2 hall bedroom		
Kitchen				
Page 8 Item: 7	GFCI	recommend -GFCI		
Exterior				
Page 20 Item: 4	Siding Condition	consult termite report		

Interior
1. Bar
Good Fair Poor N/A None
2. Cabinets
Good Fair Poor N/A None Observations: functional, worn hardware, most not accesable due to personal X Image: A state of the
3. Ceiling Fans
Good Fair Poor N/A None
4. Ceiling Condition
Good Fair Poor N/A None Materials: drywall, accoustic
X Observations: swamp cooler present, not tested by the inspector, consult the owner
5. Closets
Good Fair Poor N/A None
6. Door Bell
Good Fair Poor N/A None
7. Doors
Good Fair Poor N/A None X X A A A A
8. Electrical
Good Fair Poor N/A None Observations: some outlets n/a
9. Fireplace
Good Fair Poor N/A None
10. Floor Condition
Good Fair Poor N/A None Materials: carpet
X Observations: stained, worn, area rugs present
11. Security Bars
Good Fair Poor N/A None
12. Sliding Doors
Good Fair Poor N/A None

13. Screen Doors
Good Fair Poor N/A None
14. Smoke Detectors
Good Fair Poor N/A None X Image: A structure Image: A structure Image: A structure Image: A structure
15. Stairs & Handrail
Good Fair Poor N/A None X
16. Wall Condition
Good Fair Poor N/A None X A A A A Observations: Some areas n/a personal items, small holes
17. Window-Wall AC or Heat
Good Fair Poor N/A None X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure X Image: A structure X Image: A structure Image: A structure
18. Window Condition
Good Fair Poor N/A None Materials: aluminum X X Observations: functional, worn hardware, frame separating from the glass south LR

810 E. Rte 66 Space 132 Phoenix

Bedroom
1. Locations
Master#1, Hall#2
2. Bar
Good Fair Poor N/A None
3. Cabinets
Good Fair Poor N/A None
4. Ceiling Condition
Good Fair Poor N/A None X Image: A start of the
5. Ceiling Fans
Good Fair Poor N/A None
6. Closets
Good Fair Poor N/A None X I I I I Observations: functional, worn hardware, most n/a personal items
7. Doors
Good Fair Poor N/A None X X None Observations: functional, worn hardware, did not latch#2 hall bedroom
8. Electrical
Good Fair Poor N/A None X I I I I
9. Fireplace
Good Fair Poor N/A None
10. Floor Condition
Good Fair Poor N/A None Materials: carpet X X Dbservations: stained, worn
11. Security Bars
Good Fair Poor N/A None
12. Sliding Doors
Good Fair Poor N/A None

Page 4 of 29

13. Screen Doors
Good Fair Poor N/A None X
14. Smoke Detectors
Good Fair Poor N/A None Observations: recommend smoke dectors
15. Wall Condition
Good Fair Poor N/A None X A A A A A Observations: Some areas not accessable due to personal items, small holes
16. Window-Wall AC or Heat
Good Fair Poor N/A None
17. Window Condition
Good Fair Poor N/A None X Image: A structure Image: A structure Image: A structure Observations: functional, worn hardware

	Bathroom
1. Locations	
	Master#1, Hall#2
2. Cabinets	
	Observations: functional, worn hardware, most not accesable due to personal items
3. Ceiling Condition	
Good Fair Poor N/A None (X X A	Materials: drywall Observations: small stains#2 hall bath
4. Counters	
Good Fair Poor N/A None (Observations: normal wear
5. Doors	
Good Fair Poor N/A None (Observations: functional, worn hardware
6. Electrical	
Good Fair Poor N/A None	
7. GFCI	
Good Fair Poor N/A None (Observations: test operated, reset in the hall bathroom
8. Exhaust Fan	
Good Fair Poor N/A None	
9. Floor Condition	
Good Fair Poor N/A None (X X	Materials: vinyl Observations: stained, worn
10. Heating	
Good Fair Poor N/A None	Observations: central unit, see HVAC page
11. Mirrors	
Good Fair Poor N/A None (Observations: functional
12. Plumbing	
	Observations: worn fixtures

13. Security Bars
Good Fair Poor N/A None
14. Showers
Good Fair Poor N/A None X I I I I
15. Shower Walls
Good Fair Poor N/A None X X Image: A state of the state of
16. Bath Tubs
Good Fair Poor N/A None Observations: stained, worn, corrosion at fixtures, dirty
17. Enclosure
Good Fair Poor N/A None X X None Observations: functional, worn hardware, corrosion present, safety glass
18. Sinks
Good Fair Poor N/A None X Image: A structure in the s
19. Toilets
Good Fair Poor N/A None X Image: A state of the
20. Wall Condition
Good Fair Poor N/A None X Image: A starting starting Materials: wall paper, paneling
21. Window Condition
Good Fair Poor N/A None X A A A A Observations: functional, worn hardware

Kitchen
1. Cabinets
Good Fair Poor N/A None X Image: Second seco
2. Ceiling Condition
Good Fair Poor N/A None X Image: A state of the
3. Counters
Good Fair Poor N/A None X I I I I
4. Dishwasher
Good Fair Poor N/A None
5. Doors
Good Fair Poor N/A None
6. Electrical
Good Fair Poor N/A None X Image: Source of the second seco
7. GFCI
Good Fair Poor N/A None Observations: recommend -GFCI
8. Floor Condition
Good Fair Poor N/A None Materials: vinyl Good Fair Poor N/A None Materials: vinyl X Observations: stained, worn
9. Garbage Disposal
Good Fair Poor N/A None X X Image: A state of the state of
10. Microwave
Good Fair Poor N/A None
11. Cook top condition
Good Fair Poor N/A None Observations: operated, gas, worn unit
12. Oven & Range
Good Fair Poor N/A None Observations: operated, gas

13. Plumbing
Good Fair Poor N/A None Observations: most n/a personal items
14. Security Bars
Good Fair Poor N/A None
15. Sinks
Good Fair Poor N/A None Observations: functional, worn surface
16 Drinking Fountain
Good Fair Poor N/A None
17. Spray Wand
Good Fair Poor N/A None
18. Hot Water Dispenser
Good Fair Poor N/A None
19. Soap Dispenser
Good Fair Poor N/A None
20. Sliding Doors
Good Fair Poor N/A None
21. Screen Doors
Good Fair Poor N/A None
22. Trash Compactor
Good Fair Poor N/A None
23. Vent Condition
Good Fair Poor N/A None Materials: hood with fan
X Observations: operated, worn unit
24. Wall Condition
Good Fair Poor N/A None Materials: wall paper, paneling
X Observations: some areas n/a personal items

25. Window Condition					
Good	Fair	Poor	N/A	None	Materials: aluminum
X					Observations: functional, worn hardware

810 E. Rte 66 Space 132 Phoenix

Laundry
1. Locations
2. Cabinets
Good Fair Poor N/A None X Image: Second Seco
3. Counters
Good Fair Poor N/A None
4. Ceiling Condition
Good Fair Poor N/A None Materials: drywall, accoustic
5. Dryer Vent
Good Fair Poor N/A None X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure X Image: A structure X Image: A structure
6. Electrical
Good Fair Poor N/A None Observations: some outlets n/a
7. GFCI
Good Fair Poor N/A None
8. Exhaust Fan
Good Fair Poor N/A None
9. Doors
Good Fair Poor N/A None X I I I I
10. Floor Condition
Good Fair Poor N/A None Materials: vinyl X X Observations: worn, torn
11. Gas Valves
Good Fair Poor N/A None X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure X Image: A structure X Image: A structure
12. Plumbing
Good Fair Poor N/A None X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure X Image: A structure X Image: A structure
13. Wall Condition
Good Fair Poor N/A None X A A A A A Observations: some areas n/a personal items

Page 11 of 29

14. Wash Basin	
Good Fair Poor N/A None	
15. Window Condition	
Good Fair Poor N/A None	
16. Security Bars	
Good Fair Poor N/A None	

Heating
1. Heater Condition
Good Fair Poor N/A None Location: , laundry room X A
2. Heater Base
Good Fair Poor N/A None X I I I I
3. Enclosure
Good Fair Poor N/A None Observations: functional
4. Gas Valves
Good Fair Poor N/A None X Image: Second Seco
5. Thermostats
Good Fair Poor N/A None X I I I I
6. Venting
Good Fair Poor N/A None X I I I I
7. Filters
Good Fair Poor N/A None Inside heater X Image: A structure of the struct
8. Air Supply
Good Fair Poor N/A None X Image: Second seco
9. Registers
Good Fair Poor N/A None X I I I I
10. Refrigerant Lines
Good Fair Poor N/A None
11. AC Compress Condition
Good Fair Poor N/A None

Waterheater
1. Base
Good Fair Poor N/A None Observations: functional
2. Combusion
Good Fair Poor N/A None X Image: Second seco
3. Water Heater Condition
Good Fair Poor N/A None Materials: gas X Image: A starting of the s
4. Number Of Gallons
Good Fair Poor N/A None X I I I I
5. Heater Enclosure
Good Fair Poor N/A None X Image: Second seco
6. Gas Valve
Good Fair Poor N/A None X Image: A state of the sta
7. Overflow Condition
Good Fair Poor N/A None Materials: PVC
X
8. Plumbing
Good Fair Poor N/A None Materials: galvanized, PVC
9. Strapping
Good Fair Poor N/A None X
10. TPRV
Good Fair Poor N/A None X I I I I
11. Venting
Good Fair Poor N/A None Observations: could not fully inspect

Garage
1. Cabinets
Good Fair Poor N/A None
2. Counters
Good Fair Poor N/A None X X X X
3. Electrical
Good Fair Poor N/A None X X X X
4. GFCI
Good Fair Poor N/A None X X X X
5. 220 Volt
Good Fair Poor N/A None
6. Flooring Condition
Good Fair Poor N/A None X X X X
7. Garage Door Condition
Good Fair Poor N/A None X
8. Garage Door Parts
Good Fair Poor N/A None X
9. Garage Opener Status
Good Fair Poor N/A None X
10. Garage Door's Reverse Status
Good Fair Poor N/A None X X X X
11. Roof Condition
Good Fair Poor N/A None X
12. Exterior Door
Good Fair Poor N/A None

13. Fire Door
Good Fair Poor N/A None
14. Rafters & Ceiling
Good Fair Poor N/A None
15. Wash Basin
Good Fair Poor N/A None X X X X
16. Walls
Good Fair Poor N/A None X
17. Anchor Bolts
Good Fair Poor N/A None
18. Vent Screens
Good Fair Poor N/A None X X X X
19. Windows
Good Fair Poor N/A None X X X X

	Electrical
1. Electrical Panel	
Good Fair Poor N/A None	Main Location: , east side Sub Panel Location: , by main Observations: functional
2. Main Amp Breaker	
Good Fair Poor N/A None	Observations: 100 amp
3. Breakers in off positi	tion
Good Fair Poor N/A None	
4. Breakers	
Good Fair Poor N/A None	Materials: copper Observations: functional
5. Fuses	
Good Fair Poor N/A None	
6. Cable Feeds	
Good Fair Poor N/A None	Observations: underground
7. Main Gas Valve Co	ndition
	Materials: east side Observations: natural gas, no seismic shut off present

Roof
1. Roof Condition
Good Fair Poor N/A None X A A A A Observations: weathered
2. Chimney
Good Fair Poor N/A None
3. Flashing
Good Fair Poor N/A None Observations: not visible
4. Gutter
Good Fair Poor N/A None X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure Image: A structure Image: A structure Image: A structure X Image: A structure X Image: A structure X Image: A structure
5. Sky Lights
Good Fair Poor N/A None
6. Spark Arrestor
Good Fair Poor N/A None
7. Vent Caps
Good Fair Poor N/A None X Image: Second Seco

Attic
1. Access
Good Fair Poor N/A None Observations: no attic present
2. Chimney
Good Fair Poor N/A None X X X X X
3. Duct Work
Good Fair Poor N/A None
4. Electrical
Good Fair Poor N/A None
5. Exhaust Vent
Good Fair Poor N/A None
6. Insulation Condition
Good Fair Poor N/A None
7. Attic Plumbing
Good Fair Poor N/A None
8. Structure
Good Fair Poor N/A None
9. Ventilation
Good Fair Poor N/A None
10. Vent Screens
Good Fair Poor N/A None

Page 19 of 29

	<i>810 E</i> .	Rte 66	Space	132 P	hoenix
--	----------------	---------------	-------	-------	--------

Exterior
1. Doors
Good Fair Poor N/A None X Image: Second seco
2. Eaves & Facia
Good Fair Poor N/A None X Image: Second seco
3. Exterior Paint
Good Fair Poor N/A None X Image: Solution of the second se
4. Siding Condition
Good Fair Poor N/A None Materials: wood X X Observations: weathered, consult termite report
5. Stucco
Good Fair Poor N/A None
6. Window Condition
Good Fair Poor N/A None X Image: A state of the

Foundation
1. Slab Foundation Good Fair Poor N/A None Good Fair Poor N/A None Main X Diservations: Raised Foundation Only
2. Foundation Perimeter
Good Fair Poor N/A None
3. Ventilation
Good Fair Poor N/A None X Image: Second seco
4. Vent Screens
Good Fair Poor N/A None X Image: A state of the
5. Access Panel
Good Fair Poor N/A None X Image: Second seco
6. Post and Girders
Good Fair Poor N/A None X
7. Sub Flooring
Good Fair Poor N/A None X
8. Foundation Walls
Good Fair Poor N/A None
9. Cripple Walls
Good Fair Poor N/A None
10. Anchor Bolts
Good Fair Poor N/A None X I I I I
11. Chimney Hearth
Good Fair Poor N/A None
12. Foundation Electrical
Good Fair Poor N/A None X Image: Source of the second seco

13. Foundation Plumbing Good Fair Poor N/A None Observations: some n/a 14. Ducting Good Fair Poor N/A None Observations: functional
Good Fair Poor N/A None Observations: functional
Good Fair Poor N/A None Observations: functional

Grounds
1. Driveway and Walkway Condition
Good Fair Poor N/A None X X A A A A Observations: stained, small cracking, trip hazards, common area maintained by association
2. Patio and Porch Condition
Good Fair Poor N/A None X Image: A straight of the
3. Balcony
Good Fair Poor N/A None
4. Patio Enclosure
Good Fair Poor N/A None
5. Patio and Porch Deck
Good Fair Poor N/A None X I I I I
6. Stairs & Handrail
Good Fair Poor N/A None X I I I I
7. Grounds Electrical
Good Fair Poor N/A None X
8. GFCI
Good Fair Poor N/A None Observations: none visible
9. Fence Condition
Good Fair Poor N/A None Materials: block
10. Gate Condition
Good Fair Poor N/A None Image:
11. Grading
Good Fair Poor N/A None Observations: no drains visible, trip hazards
12. Plumbing
Good Fair Poor N/A None X Image: A starting the starting startin

13. Sprinklers
Good Fair Poor N/A None
14. Water Pressure
Good Fair Poor N/A None Observations: 70, psi
15. Pressure Regulator
Good Fair Poor N/A None X X
16. Water Shut-off Valve Condition
Good Fair Poor N/A None east side

Pool
1. Air Booster Pump
Good Fair Poor N/A None
2. Deck Condition
Good Fair Poor N/A None
3. Electrical
Good Fair Poor N/A None
4. GFCI
Good Fair Poor N/A None
5. Gate & Fence Condition
Good Fair Poor N/A None
6. Filter
Good Fair Poor N/A None
7. Skimmer and Basket
Good Fair Poor N/A None
8. Pool Heater Condition
Good Fair Poor N/A None
9. Lights
Good Fair Poor N/A None
10. Pressure Gauge
Good Fair Poor N/A None
11. Pumps
Good Fair Poor N/A None
12. Jets
Good Fair Poor N/A None

13. Structure Condition
Good Fair Poor N/A None
14. Tile
Good Fair Poor N/A None
15. Timer
Good Fair Poor N/A None
16. Water Condition
Good Fair Poor N/A None
17. Water Fill Unit
Good Fair Poor N/A None

Photos



Exterior - Gas Meter



Electrical - Service Panel



Waterheater - View





Heating - View

Electrical - Sub Panel



Foundation - View

Page 28 of 29

Residential Earthquake Hazards Report				
Yes	No	N/A	Don't Know	
Х			1. Is the water heater braced, strapped, or anchored to resist falling during an earthquake?	
Yes	No	N/A	Don't Know	
Х			2. Is the house anchored or bolted to the foundation?	
Yes	No	N/A	3. If the house has cripple walls: a. Are the exterior cripple walls braced?	
		X		
Yes	No	N/A	Don't Know	
		X	b. If the exterior foundation consists of unconnected concrete piers and posts, have they been strengthened?	
N	N	N 1/A		
Yes	No	N/A	4. If the exterior foundation, or part of it, is made of unreinforced masonry, has	
		X	it been strengthened?	
Yes	No	N/A	Don't 5. If the house is built on a hillside:	
		X	a. Are the exterior tall foundation walls braced?	
Yes	No	N/A	Don't	
			b. Were the tall posts or columns either built to resist earthquakes or have	
		X	they been strengthened?	
Yes	No	N/A	Don't Know	
		Х	6. If the exterior walls of the house, or part of them, are made of unreinforced	
	N	N 1/A	masonry, have they been strengthened?	
Yes	No	N/A	7. If the house has a living area over the garage, was the wall around the	
		X	garage door opening either built to resist earthquakes or has it been strengthened?	
Yes	No		Don't	
]	$\frac{1}{X}$ 8. Is the house outside an Alquist-Priolo Earthquake Fault Zone (zones	
		J	immediately surrounding known earthquake faults)?	
Yes	No		Don't Know	
			X 9. Is the house outside a Seismic Hazard Zone (zone identified as susceptible to liquefaction or landsliding)?	
	<u>-</u>	- - · ·		
EXEC	JUTE	U BY		
(Selle	er)		(Seller) Date	
I acknowledge receipt of this form, completed and signed by the seller. I understand that if the seller has answered "No" to one or more questions, or if seller has indicated a lack of knowledge, there may be one or more earthquake weaknesses in this house.				
(Buye	er)		(Buyer) Date	