## Accurate Home Inspections Property Inspection Report



1221 N. Harvest Walk Dr, La Puente CA, 91555 Inspection prepared for: John Felix & Jan Felix Agent: Jane Smith - Smith Realty

Inspection Date: 8/1/2007 Time: 3:30 to 5:45 Age: 1980 Size: 1500 square feet Weather: Sunny


Inspector: John P. Inspector



Inspection Services, LLC

## **Report Summary**

Attic				
Page 3 Item: 5	Exhaust Vent	Several of the bathroom exhaust pipes terminate in the attic. This can cause a buildup of moisture and eventually mold in the attic.		
Electrical				
Page 8 Item: 1	Electrical Panel	There was evidence of water within the panel., I reccommend having a licensed electrician evaluate., 14 gauge wire runs to a 30 amp breaker, improper electrical installation, Undersized wires to a breaker.		
Page 9 Item: 7	Main Gas Valve Condition	No seismic shut off present., I recommend having the Gas Company evaluate the valve.		
Garage				
Page 14 Item: 13	Fire Door	The fire door from the garage to the kitchen did not self close and latch		
Grounds	1			
Page 16 Item: 13	Sprinklers	Visible leaking of sprinker valves.		
Heating	1			
Page 17 Item: 1	Heater Condition	The unit does not have proper clearence. The walls to it's side are too close		
Page 18 Item: 7	Filters	Filters were dirty. I recommend replacing the filters to ensure proper function of the heating system		
Interior				
Page 20 Item: 14	Smoke Detectors	Two of the interior smoke detectors did not operate.		
Kitchen	-			
Page 21 Item: 4	Dishwasher	Some water discharged out of the air gap during operation.		
Page 21 Item: 5	Doors	The door did not have a latch to the exterior.		
Page 22 Item: 17	Spray Wand	The spray was irregular, it should be replaced.		
Waterheater				
Page 28 Item: 3	Water Heater Condition	Evidence of leaking was seen on the water heater base.		
Page 28 Item: 7	Plumbing	The water heater shut off handle was missing. This should be repaired by a licensed plumber.		



5. Exhaust Vent
Good       Fair       Poor       N/A       None         X       X       Several of the bathroom exhaust pipes terminate in the attic. This can cause a buildup of moisture and eventually mold in the attic.
6. Insulation Condition
Good       Fair       Poor       N/A       None         X       A       A       A       A         Materials:       fiberglass       batts         Materials:       6, inches
7. Attic Plumbing
Good       Fair       Poor       N/A       None         X       Image: A structure       Image: A s
8. Structure
Good       Fair       Poor       N/A       None         X       Image: Second seco
9. Ventilation
Good       Fair       Poor       N/A       None         X       Image: Second seco
10. Vent Screens
Good Fair Poor N/A None Observations: All the vent screens in the attic are present and in good

X condition.

### Bathroom

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, walpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

### 1. Locations

Materials: Master#1, Hall#2

2. Cabinets
Good Fair Poor N/A None Observations: All cabinets in the home are fully functional.
3. Ceiling Condition
Good       Fair       Poor       N/A       None         X       Image: A starting of the
4. Counters
Good       Fair       Poor       N/A       None         X       I       I       I       I
5. Doors
X Fair Poor N/A None Observations: All doors in the home are fully functional.
6. Electrical
Good Fair Poor N/A None
7. GFCI
Good       Fair       Poor       N/A       None         X       Image: Solution of the second of
8. Exhaust Fan
Good Fair Poor N/A None Observations: The exahaust fan operated normally.
9. Floor Condition
Good       Fair       Poor       N/A       None         X       X       Materials: carpet, tile         Observations: The carpets were worn and stained in several areas.
10. Heating
Good Fair Poor N/A None Observations: Heating is controlled via central unit. Please see the Heating & Air Conditioning page.
11. Mirrors
Good       Fair       Poor       N/A       None         X       I
12. Plumbing
Good     Fair     Poor     N/A     None       X

13. Security Bars
Good Fair Poor N/A None
14. Showers
Good       Fair       Poor       N/A       None         X       Image: Second Fair       Poor       N/A       None         Description       Second Fair       Poor       N/A       None         Image: Second Fair       Poor       N/A       None       Observations: The shower, including the drain and all its hardware is fully         Image: Second Fair       Image: Second Fair       Image: Second Fair       Image: Second Fair         X       Image: Second Fair       Image: Second Fair       Image: Second Fair         Image: Second Fair       Image: Second Fair       Image: Second Fair       Image: Second Fair         X       Image: Second Fair       Image: Second Fair       Image: Second Fair       Image: Second Fair         X       Image: Second Fair       Image: Second Fair       Image: Second Fair       Image: Second Fair         X       Image: Second Fair       Image: Second Fair       Image: Second Fair       Image: Second Fair         X       Image: Second Fair       Image: Second Fair       Image: Second Fair       Image: Second Fair         X       Image: Second Fair       Image: Second Fair       Image: Second Fair       Image: Second Fair         X       Image: Second Fair       Image: Second Fair       Image: Second Fair       Image:
15. Shower Walls
Good       Fair       Poor       N/A       None         X       I
16. Bath Tubs
Good       Fair       Poor       N/A       None         X       Image: Second seco
17. Enclosure
Good Fair Poor N/A None Observations: The enclosure consisted of a curtain.
18. Sinks
Good       Fair       Poor       N/A       None         X       I
19. Toilets
Good       Fair       Poor       N/A       None         X       Image: Second seco
20. Wall Condition
Good       Fair       Poor       N/A       None         X       I       I       I       I
21. Window Condition
Good       Fair       Poor       N/A       None         X       All other windows are functional.       All other windows are functional.

### Bedroom

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

1. Locations
Materials: Master, South#2, North#3
2. Bar
Good Fair Poor N/A None
3. Cabinets Good Fair Poor N/A None
Good Fair Poor N/A None
4. Ceiling Condition
5. Ceiling Fans
Good Fair Poor N/A None
6. Closets
X None Observations: The closets are fully functional.
7. Doors
X   Observations: The doors are fully functional.
8. Electrical
Good Fair Poor N/A None Observations: Some of the outlets in the bedroom were not accessable.
X     All other outlets were functional.
9. Fireplace
Good Fair Poor N/A None
10. Floor Condition
Good       Fair       Poor       N/A       None         X       A       A       A       A         Observations:       The bedroom floors were stained and worn.
11. Security Bars Good Fair Poor N/A None
12. Sliding Doors
Good Fair Poor N/A None

# 1221 N. Harvest Walk Dr, La Puente

13. Screen Doors Good Fair Poor N/A None
14. Smoke Detectors
Good       Fair       Poor       N/A       None         X       Image: Second seco
15. Wall Condition
Good       Fair       Poor       N/A       None         X       Image: Solution of the state of th
16. Window-Wall AC or Heat
Good       Fair       Poor       N/A       None         Image:
17. Window Condition
Good       Fair       Poor       N/A       None         X       Image: Second seco

Electri	cal
1. Electrical Panel	
within the panel., I reccomme	es to a breaker., There was evidence of water nd having a licensed electrician evaluate., 14 breaker, improper electrical installation,
Electrical Panel	Electrical Sub Panel
2. Main Amp Breaker	
Good     Fair     Poor     N/A     None       X     Image: Source of the second	
3. Breakers in off position	
Good     Fair     Poor     N/A     None       X         Observations: 0	
4. Breakers	
Good         Fair         Poor         N/A         None           X         A         A         Observations: All breakers we	ere functional.
5. Fuses Good Fair Poor N/A None X	
6. Cable Feeds	
Good Fair Poor N/A None Observations: Electrical cable	e feeds were located underground.
7. Main Gas Valve Condition	
	he house is natural gas., No seismic shut off the Gas Company evaluate the valve.



Main Gas Valve

Exterior
1. Doors
Good       Fair       Poor       N/A       None         X       Image: No water damage was noticed.       No water damage was noticed.
2. Eaves & Facia
Good Fair Poor N/A None Observations: The facia had several small cracks., Boards appeared to be weathered.
3. Exterior Paint
Good Fair Poor N/A None Observations: Exterior paint was peeling in several places.
4. Siding Condition
Good       Fair       Poor       N/A       None
5. Stucco
Good Fair Poor N/A None Observations: Stains and small cracks were found.,
6. Window Condition
Good       Fair       Poor       N/A       None         X       Image: Second Seco

Foundation
1. Slab Foundation
Good Fair Poor N/A None Observations: Part of the slab not visible due to floor coverings.
2. Foundation Perimeter
Good Fair Poor N/A None Observations: The foundation perimeter is partially visible.
3. Ventilation
Good Fair Poor N/A None
4. Vent Screens
Good Fair Poor N/A None
5. Access Panel Good Fair Poor N/A None
6. Post and Girders
Good Fair Poor N/A None
Foundation view Foundation view
7. Sub Flooring
Good Fair Poor N/A None
8. Foundation Walls
Good Fair Poor N/A None
9. Cripple Walls
Good Fair Poor N/A None

Х

#### 10. Anchor Bolts N/A

Good	Fair	Poor


None Observations: No anchor bolts were visible. The foundation was not accessible.

### 11. Chimney Hearth



### 12. Foundation Electrical

Fair	Poor	N/A	None
			X
	Fair	Fair Poor	Fair Poor N/A




Exposed electrical connections. Missing junction box cover.

## 13. Foundation Plumbing

Good	Fair	Poor	N/A	None	Observations: The foundation plumbing could not be accessed.
			Х		
			<i>/</i> \		



Foundation Plumbing



1221 N. Harvest Walk Dr, La Puente

Garage
1. Cabinets
Good Fair Poor N/A None
2. Counters
Good Fair Poor N/A None
3. Electrical
Good     Fair     Poor     N/A     None       X
4. GFCI
X Fair Poor N/A None Observations: The GFCI in the garage operates normally.
5. 220 Volt
Good Fair Poor N/A None Observations: A 220 volt socket could not be found.
6. Flooring Condition
Good     Fair     Poor     N/A       X
7. Garage Door Condition
Good         Fair         Poor         N/A         None           X         Observations:         Garage door functions normally.
8. Garage Door Parts
Good     Fair     Poor     N/A     None       X     Image: Source of the second
9. Garage Opener Status
Good     Fair     Poor     N/A     None       X     Image: Second
10. Garage Door's Reverse Status
Good       Fair       Poor       N/A       None         X       I       I       I       I
11. Roof Condition
Good Fair Poor N/A None Materials: same as the main structure
12. Exterior Door
Good       Fair       Poor       N/A       None         X       I       I       I       I
13. Fire Door
Good Fair Poor N/A None Observations: The fire door from the garage to the kitchen did not self close and latch

1221 N. Harvest Walk Dr, La Puente

14. Rafters & Ceiling
Good Fair Poor N/A None Observations: Garage rafters were not designed for heavy storage.
15. Wash Basin
Good Fair Poor N/A None
16. Walls
Good     Fair     Poor     N/A     None       X
17. Anchor Bolts
Good Fair Poor N/A None Observations: Anchor bolts were not accesible.
18. Vent Screens
Good       Fair       Poor       N/A       None         X       Image: Second Seco
19. Windows
Good Fair Poor N/A None

Grounds						
1. Driveway and Walkway Condition						
Good       Fair       Poor       N/A       None         X       A       A       A       A         Observations:       There are quite a few oil stains on the driveway.         There were small cracks in the driveway.         The sidewalk was elevated in several places which is a trip hazard.						
2. Patio and Porch Condition						
Good       Fair       Poor       N/A       None         X       A       A       A       A         Observations:       The patio was functional.       B         Some weathering of the patio was seen.       Some weathering of the patio was seen.						
3. Balcony						
Good Fair Poor N/A None						
4. Patio Enclosure						
Good Fair Poor N/A None						
5. Patio and Porch Deck						
Good       Fair       Poor       N/A       None         X       Image: State of the s						
6. Stairs & Handrail						
Good Fair Poor N/A None						
7. Grounds Electrical						
Missing wire nuts						
8. GFCI						
Good       Fair       Poor       N/A       None         X       Image: Second seco						

9. F	ence	Cor	nditic	on		
Good	Fair X	Poor	N/A	None	Materials: block, wood Observations: Some weathering was noticed on the fence. There is contact between the earth and wood. This can cause ter problems.	mite
					The fence could not be fully inspected due to plant growth.	
	Gate					
Good	Fair	Poor	N/A	None	Materials: wood Observations: The gate was fully functional. The hardware was a bit old and worn.	
11.	Grad	ling				
Good	Fair X	Poor	N/A	None	Observations: No drains were visible in the area. Signs of poor drainage were present. The grading was elevated in several places which is a trip hazard	l
12.	Plum	bing				
Good	Fair	Poor	N/A	None	Materials: copper	
13.	Sprir	kler	S			
Good	Fair X	Poor	N/A	None	Observations: The sprinklers are on a timer system. The system was tested and worked. Visible leaking of sprinker valves.	
					<image/> <caption></caption>	
14. Good		Poor	essu	None		
X					Observations: 75, psi	
	Pres		-			
Good	Fair	Poor	N/A	None	Observations: The pressure regular was present, but not tested.	
16.	Wate	er Sh	ut-o	ff Va	Ive Condition	
Good	Fair	Poor	N/A	None	Materials: garage	
						Page 16 of 3 <sup>-</sup>

### Heating

The heating, ventillation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventillation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Heater Condition Good Fair Poor N/A None Materials: Location: , attic X None Materials: gas, forced, split sys Observations: The water heater clearence. The walls to it's side	tem r was functional. The unit does not have proper a are too close
Heater	Heating Heater Condition
2. Heater Base	
3. Enclosure	
4. Gas Valves Good Fair Poor N/A None X Deservations: The water heater	r gas valves were functional
5. Thermostats	
Good     Fair     Poor     N/A     None       X	operated normally
6. Venting	
5	not be fully inspected due to personal items in
	Page 17 of 31

7. Filters
Good       Fair       Poor       N/A       None         X       Deservations:       Filters were dirty.       I recommend replacing the filters to ensure         Proper function of the heating system
8. Air Supply
Sood Fair Poor N/A None Observations: The air supply was functional and in a good location
9. Registers
Good       Fair       Poor       N/A       None         X       Image: Second Seco
10. Refrigerant Lines
Good       Fair       Poor       N/A       None         X       Image: Second Seco
11. AC Compress Condition
Good       Fair       Poor       N/A       None         X       Aterials:       Patrice       Materials:       Patrice         Materials:       patio       area       Observations:       A/C       Compressor       Operated       at 49 degrees

Heating AC Compress Condition

### Interior

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The insector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Bar
Good Fair Poor N/A None
2. Cabinets
Good       Fair       Poor       N/A       None         X       Image: Second Seco
3. Ceiling Fans
Good     Fair     Poor     N/A     None
4. Ceiling Condition
Good       Fair       Poor       N/A       None         X       Image: A starting of the
5. Closets
Good       Fair       Poor       N/A       None         X       Image: Second seco
6. Door Bell
Good       Fair       Poor       N/A       None         X       Image: Source of the second seco
7. Doors
Good       Fair       Poor       N/A       None         X       Image: Source of the second seco
8. Electrical
X Fair Poor N/A None Observations: Some of the outlets in the interior were not accessible.
9. Fireplace
Good       Fair       Poor       N/A       None         X       Materials:       prefabricated         Observations:       The fireplace is gas only.
10. Floor Condition
Good       Fair       Poor       N/A       None         X       A       A       A       B         Observations:       The interior carpeting and tile is stained and worn.

11. Security Bars
Good Fair Poor N/A None
12. Sliding Doors
Good Fair Poor N/A None
13. Screen Doors
Good     Fair     Poor     N/A     None       Image: State Stat
14. Smoke Detectors
Good       Fair       Poor       N/A       None         X       I
15. Stairs & Handrail
Good     Fair     Poor     N/A     None
16. Wall Condition
Good       Fair       Poor       N/A       None         X       A       A       A       A         Observations:       Some areas of the wall were not visible due to personal items.
17. Window-Wall AC or Heat
Good Fair Poor N/A None
18. Window Condition
Good       Fair       Poor       N/A       None         X       Image: State of the s

### Kitchen

The kitchen is used for food preperation and often for entertainment. Kitchens tyically include a stove, dishwasher, sink and other appliances.

1. Cabinets
Good       Fair       Poor       N/A       None         X       Image: Source of the second seco
2. Ceiling Condition
Good Fair Poor N/A None Materials: drywall
3. Counters
Good Fair Poor NA None Observations: There was normal wear on the tile counters.
4. Dishwasher
Good Fair Poor N/A None Observations: The dishwater operated.
X Some water discharged out of the air gap during operation.
5. Doors
Good Fair Poor NA None Observations: The door did not have a latch to the exterior.
6. Electrical
Good Fair Poor N/A None Observations: Some of the kitchen outlets were not accessible due to
X appliances.
7. GFCI
X None Observations: The GFCI tested operational.
8. Floor Condition
Good     Fair     Poor     N/A     None       X     A     A     A     A
9. Garbage Disposal
X None Observations: The disposal operated normally.
10. Microwave
Good Fair Poor N/A None
11. Cook top condition
X Solution N/A None Observations: The gas cooktop operated normally.
12. Oven & Range
X Sood Fair Poor N/A None Observations: The gas oven was operational.

13. Plumbing Good Fair Poor N/A None X
14. Security Bars       Good Fair Poor N/A None       Good     Fair     Poor N/A     None       X     X
15. Sinks         Good Fair Poor N/A None         Observations: The sinks were functional.         X       The fixtures and the surface of the sink were worn.         Rust was found on the sink fixtures.         There were several chips in the sink itself.
16. Drinking Fountain Good Fair Poor N/A None X Deservations: The fresh water dispenser operated normally.
17. Spray Wand         Good       Fair       Poor       N/A       None         Observations: The spray wand operated.         X       The spray was irregular, it should be replaced.
18. Hot Water Dispenser         Good       Fair       Poor       N/A       None         Image: State of the
19. Soap Dispenser Good Fair Poor N/A None X
20. Sliding Doors         Good Fair Poor N/A None         Image: Colspan="3">Image: Colspan="3">Image: Colspan="3">Image: Colspan="3">Image: Colspan="3">Image: Colspan="3"         Good Fair       Poor       N/A       None         Image: Colspan="3">Image: Colspan="3"         Image: Colspan="3"       Image: Colspan="3"         Image: Colspan="3"       Image: Colspan="3"         Image: Colspan="3"       Image: Colspan="3"         Image: Colspan="3">Image: Colspan="3"
21. Screen Doors Good Fair Poor N/A None X
22. Trash Compactor
23. Vent Condition Good Fair Poor N/A None X N/A None Materials: self filtering with vent to the exterior Observations: The vent operated normally.
24. Wall Condition         Good       Fair       Poor       N/A       None         X       Image: Second
25. Window Condition         Good       Fair       Poor       N/A       None         X       Image: Second Secon

Laundry
1. Locations
Materials: In the garage area
2. Cabinets Good Fair Poor N/A None
Good     Fair     Poor     N/A     None       Image:
3. Counters
Good       Fair       Poor       N/A       None         Image:
4. Ceiling Condition
Good Fair Poor N/A None Materials: drywall
5. Dryer Vent
Good     Fair     Poor     N/A     None       X     Image: A structure     Image: A structure     Image: A structure
6. Electrical
Good     Fair     Poor     N/A     None       X
7. GFCI
Good Fair Poor N/A None
8. Exhaust Fan
Good     Fair     Poor     N/A     None       Image: State Stat
9. Doors
Good     Fair     Poor     N/A     None       Image: Constraint of the state of the st
10. Floor Condition
Good Fair Poor N/A None Materials: concrete
11. Gas Valves
Good       Fair       Poor       N/A       None         X       Image: Second seco
12. Plumbing
Good Fair Poor N/A None Observations: The plumbing was not tested.
13. Wall Condition
Good Fair Poor N/A None Materials: drywall

14. Wash Basin		
Good Fair Poor N/A None		
15. Window Condition		
Good Fair Poor N/A None		
16. Security Bars		
Good Fair Poor N/A None		

Pool
1. Air Booster Pump Good Fair Poor N/A None
2. Deck Condition
Good Fair Poor N/A None
3. Electrical
Good Fair Poor N/A None
4. GFCI
Good Fair Poor N/A None
5. Gate & Fence Condition
Good Fair Poor N/A None
6. Filter
Good     Fair     Poor     N/A     None
7. Skimmer and Basket
Good Fair Poor N/A None
8. Pool Heater Condition
Good Fair Poor N/A None
9. Lights
Good Fair Poor N/A None
10. Pressure Gauge
Good     Fair     Poor     N/A     None
11. Pumps
Good     Fair     Poor     N/A     None
12. Jets
Good Fair Poor N/A None
13. Structure Condition
Good     Fair     Poor     N/A     None

14. Tile
Good Fair Poor N/A None
15. Timer
Good Fair Poor N/A None
16. Water Condition
Good Fair Poor N/A None
17. Water Fill Unit
Good Fair Poor N/A None

Roof						
1. Roof Condition						
Good Fair Poor N/A None Materials: tile Observations: The roof was not accessible due to type of roofing materials. The roof was inspected from ground only						
2. Chimney						
Good Fair Poor N/A None Observations: The chimney was accessible due to type of roofing material The chimeney was inspected from the ground only.						
3. Flashing						
Good Fair Poor N/A None Observations: The flashing was not accessible.						
4. Gutter						
Good Fair Poor N/A None Observations: There were no rain gutters attached to the roof. Rain gutters are recommended to prevent damage to the structure.						
5. Sky Lights						
Good Fair Poor N/A None						
6. Spark Arrestor						
Good Fair Poor N/A None Observations: The spark arrestor was present. Could not access due to height						
7. Vent Caps						
Good Fair Poor N/A None Observations: The vent caps were functional.						

# 1221 N. Harvest Walk Dr, La Puente

Waterheater							
1. Base							
2. Combusion							
Good Fair Poor N/A None Observations: Combustion operated normally.							
3. Water Heater Condition							
Good       Fair       Poor       NA       None         Materials:       garage         Observations:       Water heater operated normally., Evidence of leaking was seen on the water heater base.							
Water Heater							
4. Heater Enclosure							
Good Fair Poor N/A None							
5. Gas Valve Good Fair Poor N/A None X Deservations: The gas valve operated normally.							
6. Overflow Condition Good Fair Poor N/A None X N/A None Materials: copper							
7. Plumbing Good Fair Poor N/A None Materials: copper X Observations: Insulation was present around the plumbing The water heater shut off handle was missing. This should be repaired by a licensed plumber.							
8. Strapping         Good       Fair       Poor       N/A       None         X       V       V       V       V							

9. TPRV
Good       Fair       Poor       N/A       None         X       Image: Second seco
10. Venting
Good       Fair       Poor       N/A       None         X       Image: Source of the second seco
Impropriate for the time is the beganned and
Improper installation of vent pipe. Exhaust vent from water heating in the basement area.
11 Number of Gallons

Materials: 40 gallons

# Photos



Exterior

Residential Earthquake Hazards Report							
Yes	No	N/A	Don't Know				
X			1. Is the water heater braced, strapped, or anchored to resist falling during earthquake?	) an			
Yes	No	N/A	Don't Know				
Х			2. Is the house anchored or bolted to the foundation?				
Yes	No	N/A	<ul> <li>Don't Know</li> <li>3. If the house has cripple walls:</li> <li>a. Are the exterior cripple walls braced?</li> </ul>				
		X					
Yes	No	N/A	Don't Know	-1			
		X	b. If the exterior foundation consists of unconnected concrete piers and posts, have they been strengthened?	a			
Yes	No	N/A	Don't				
		X	4. If the exterior foundation, or part of it, is made of unreinforced masonry, it been strengthened?	has			
Yes	No	N/A	5. If the house is built on a hillside:				
		X	a. Are the exterior tall foundation walls braced?				
Yes	No	N/A	Don't				
			b. Were the tall posts or columns either built to resist earthquakes or ha	ave			
		X	they been strengthened?				
Yes	No	N/A	Don't Know	_			
		X	6. If the exterior walls of the house, or part of them, are made of unreinford masonry, have they been strengthened?	ced			
Yes	No	N/A					
		X	$\frac{Know}{2}$ 7. If the house has a living area over the garage, was the wall around the				
			garage dooropening either built to resist earthquakes or has it been strengthened?				
Yes	No		Don't Know				
Χ		]	8. Is the house outside an Alquist-Priolo Earthquake Fault Zone (zones immediately surrounding known earthquake faults)?				
Yes	No		Don't				
X		]	9. Is the house outside a Seismic Hazard Zone (zone identified as suscept to liquefication or landsliding)?	tible			
EXEC	CUTE	D BY					
(Selle	er)		(Seller) Date				
I acknowledge receipt of this form, completed and signed by the seller. I understand that if the seller has answered "No" to one or more questions, or if seller has indicated a lack of knowledge, there may be one or more earthquake weaknesses in this house.							
(Buye	ər)		(Buyer) Date				